

Member Advisory

DATE: March, 23 2023 **NUMBER:** MA 23-02

FROM: Club Racing Board

TO: All Participants

SUBJECT: Elan DP02

It has been brought to our attention that an Elan DP02 had a shoulder harness hardware mounting failure in the last several months while participating in a non-SCCA event. This specific failure involved the stud between the two brackets fastened to the tub. The vehicle had 2" shoulder harnesses installed.

The DP02 shared the same tub as the Pro Formula Mazda car that many continue to run in Formula Atlantic.

We share this information with our racing community in the interest of safety and transparency.