

NUMBER:	MA 22-02
DATE:	May 18, 2022
FROM:	Club Racing Board
TO:	All Participants
SUBJECT:	ATL Discriminator Vent Valve Recall

The Club Racing Board has been made aware that Aero Tec Laboratories (ATL) has issued a recall on the Discriminator Valve.



May 17, 2022

Product Recall- Aero Tec Laboratories Inc (ATL) Ramsey , NJ Part Number RE 185 ATL “Discriminator” Vent Valve

Effective immediately, ATL is issuing a product recall for all Part Number RE 185 ATL “Discriminator” Vent Valves that were purchased between September 1, 2021, and May 2022.

As a result of a change in the plastic resin, some discriminator valve bodies have cracked / broken after exposure to fuel/ fuel vapor. It is suspected that elevated temperatures and vibration in this fuel-rich environment could also be a contributing factor to failure.

Due to a risk of fire that could result from using a damaged vent valve, it is MANDATORY that all RE 185 ATL “Discriminator” Vent Valves purchased during the above outlined period, be immediately taken out of service and returned to ATL for a refund.

For those ATL distributors that have re-sold these RE185 Discriminator Valves, we ask that you in turn alert your customers to this recall and more importantly to alert them to the potential danger associated with using this one lot of RE 185 ATL “Discriminator” Vent Valves. We seek your assistance in insisting upon the return of these recalled parts.

ATL Point of Contact-
David Dack
Tel 201-825-1400
e-mail; ddack@atlinc.com
Please return these parts to :
Aero Tec Laboratories Inc (ATL)
45 Spear Road
Ramsey, NJ 07663
Attn. RE185



For additional details, contact the tech department at SCCA.

800-770-2055
tech@scca.com

Thank you,
Club Racing Board