

Member Advisory
Technical Services
MA 22-01

NUMBER:	MA 22-01
DATE:	April 12, 2022
FROM:	Club Racing Board
то:	All Participants
SUBJECT:	Prototype SIR Compliance

The Club Racing Board has become aware that P1 competitors are attempting to defeat the SIR stall test by programming the ECU to shut down the engine when it senses a drop in RPM to avoid the detection of controlled leaks in the air box. The rules clearly state that the introduction of air behind the SIR by any means is prohibited.

The CRB is developing innovative methods for detection and requests that the Stewards of the Meeting (SOM) employ zero tolerance in connection with any SIR infractions or attempts to defeat the SIR stall test.

For additional details, contact the tech department at SCCA.

800-770-2055 tech@scca.com

Thank you, Club Racing Board